



July 20, 2021

United States Environmental Protection Agency
Air Compliance Branch
290 Broadway, 21st Floor
New York, NY 10007-1866

Attn.: NESHAP COORDINATOR

JOHN F. KENNEDY INTERNATIONAL AIRPORT – BUILDING 111
1ST & 2ND & 3RD FLOOR – WOMEN AND MEN BATHROOM


OPERATOR PROJECT #: 1076A.02

Dear Madam/Sir:

Our courtesy notification for the abatement work to be done at the above referenced location is attached.

If you have any questions, please contact me at 718-244-4546.

Sincerely,



Norman Clayton
Field Supervisor
Environmental Field Operations
Construction Management Division

cc: Project File (EPA-2788)
Non-RACM Notification File

RC/fl

**U.S. Environmental Protection Agency
Notification of Demolition and Renovation**

Operator Project #: 1076A.02		Postmark:		Date Received: 07/20/2021		Notification #: EPA-2788	
I. Type of Notification (O=Original R=Revised C=Canceled) <input type="radio"/>							
II. Facility Information (Identify owner, removal contractor, and other operator)							
Owner Name: THE PORT AUTHORITY OF NY & NJ							
Address: 241 ERIE ST. ROOM 236							
City: JERSEY CITY				State: NJ		Zip: 07310	
Contact: N. CLAYTON, FACILITY SUPERVISOR, ASBESTOS OPS				Telephone: 718-244.4565			
Removal Contractor: INTERNATIONAL ASBESTOS REMOVAL, INC							
Address: 119 COOPER STREET							
City: BABYLON				State: NY		Zip: 11702	
Contact: KAREN GRANDO				Telephone: 718-335-0304			
Other operator:							
Address:							
City:				State:		Zip:	
Contact:				Telephone:			
III. Type of Operation (D=Demo O=Ordered Demo R=Renovation E=Emergency) <input checked="" type="radio"/>							
IV. Is Asbestos Present? (Yes/No) YES							
V. Facility Description (include building name, number, floor, and /or room number):							
Building Name: JOHN F. KENNEDY INTERNATIONAL AIRPORT							
Address:							
City: JAMACIA				State: NY		County: QUEENS	
Site Location: BUILDING # 111, 1ST & 2ND & 3RD FLOOR WOMEN AND MEN BATHROOM							
Building Size: 500000				# of Floors:		Age in Years: 70+	
Present Use: COMMERCIAL				Prior Use: COMMERCIAL			
VI. Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material:							
VII. Approximate Amount of Asbestos, Including:							
1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed			Non-RACM To Be Removed	RACM to Be Removed	Nonfriable Asbestos Materials Not To Be Removed		Indicate Measurement
					Cat I	Cat II	
Pipes			1600 LN.FT				Lnft: 1,600
Surface Area							Sqft: 0
Vol RACM Off Facility Component							Cuft: 0
VIII. Scheduled Dates Asbestos Removal				Start: 08/02/2021		Complete: 12/20/2021	
IX. Scheduled Dates Demo/Renovation				Start:		Complete:	

**U.S. Environmental Protection Agency
Notification of Demolition and Renovation**

X. Description of Planned Demolition or Renovation Work, and Method(s) to Be Used:

FULL CONTAINMENT PIPE INSULATION ABATEMENT UTILING MANUAL METHODS. NEGATIVE AIR UNITS WILL BE UTILIZED IN LINE WITH CODE RULE 56 NYSDOL RULES AND REGULATIONS. ALL PART 56 OF TITLE 12 NYSDOL RULES AND REGULATIONS WILL BE FOLLOWED

XI. Description of Work Practices and Engineering Controls to Be Used to Prevent Emissions Of Asbestos At the Demolition And Renovation Site:

XII. Waste Transporter #1

Name: CARDELLA TRUCKING

Address: 2400 TONNELLE AVENUE

City: NORTH BERGEN

State: NJ

Zip: 07047

Contact:

Telephone: 201-867-7276

Waste Transporter #2

Name:

Address:

City:

State:

Zip:

Contact:

Telephone:

XIII. Waste Disposal Site

Name: WASTE MANAGEMENT OF FAIRLESS, LLC

Location: 1000 NEW FORD MILL ROAD

City: MORRISVILLE

State: PA

Zip: 44688

Telephone: 484-250-5768

XIV. If Demolition Ordered By a Government Agency, Please Identify the Agency Below

Name:

Title:

Authority:

Date of Order:

Date Ordered To Begin:

XV. For Emergency Renovations

Date and Hour of Emergency:

Description of Sudden or Unexpected Event:

Explanation of How the Event Caused Unsafe Conditions or Would Cause Equipment Damage or an Unreasonable Financial Burden:

XVI. Descriptions of Procedures to Be Followed in the Event That Unexpected Asbestos Is Found or Previously Nonfriable Asbestos Material Becomes Crumbled, Pulverized or Reduced to Powder:
IMMEDIATE ISOLATION OF THE AREA AND ADEQUATE WETTING OF ASBESTOS MATERIAL FOLLOWED BY HEPA VACUUMING AND WET WIPING ALL AFFECTED AREAS

XVII. I Certify That an Individual Trained in the Provisions of This Regulation (40 CFR Part 61, Subpart M) Will Be On-Site During the Demolition or Renovation And Evidence That the Required Training Has Been Accomplished by This Person Will Be Available for inspection

(Signature of Owner/Operator)

7/21/21
(Date)

XVIII. I Certify That the Above Information Is Correct.

(Signature of Owner/Operator)

7/21/21
(Date)